



basic education

Department:
Basic Education
REPUBLIC OF SOUTH AFRICA

SENIOR CERTIFICATE EXAMINATIONS/ NATIONAL SENIOR CERTIFICATE EXAMINATIONS

MECHANICAL TECHNOLOGY: WELDING AND METALWORK

2022

MARKING GUIDELINES

MARKS: 200

These marking guidelines consist of 19 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)

- | | | |
|-----|-----|------------|
| 1.1 | A ✓ | (1) |
| 1.2 | B ✓ | (1) |
| 1.3 | C ✓ | (1) |
| 1.4 | D ✓ | (1) |
| 1.5 | A ✓ | (1) |
| 1.6 | C ✓ | (1) |
| | | [6] |

QUESTION 2: SAFETY (GENERIC)

2.1 Rated speed of a grinding wheel:

- Because the wheel could burst/break if it turns faster than its revolution range. / Avoid an accident. ✓
- Effectiveness of the grinding process will be compromised. ✓ **(Any 1 x 1)** (1)

2.2 Safety precautions of a band saw in operation:

- Never leave the band saw unattended. ✓
- Use a push stick when cutting. ✓
- Hold the work piece firmly and flat on the table. ✓
- Don't adjust the machine while working. ✓
- Don't open any guard while the machine is on. ✓
- Make relief cuts before cutting tight curves. ✓
- Don't force the material into the blade. ✓
- Keep hands clear from the action point. ✓
- Keep hands braced against the table. ✓
- Keep your hands on either sides of the blade and not in line with the cutting line and the blade. ✓
- Keep loose clothing clear from action point. ✓ **(Any 2 x 1)** (2)

2.3 Stages in which first aid is applied:

- Examination ✓
- Diagnosis ✓
- Treatment ✓ (3)

2.4 Causes of accidents:

- Unsafe acts ✓
- Unsafe conditions ✓ (2)

2.5 TWO advantages of the product layout:

- Handling of material is kept to a minimum. ✓
 - Time period of manufacturing cycle is less. ✓
 - Production control is almost automatic. ✓
 - Control over operations is easier. ✓
 - Greater use of unskilled labour is possible. ✓
 - Less total inspection is required. ✓
 - Less total floor space is needed per unit of production. ✓ **(Any 2 x 1)** (2)
- [10]**

QUESTION 3: MATERIALS (GENERIC)

- 3.1 **Tempering:**
Tempering is a process generally applied to steel to relieve the strains/brittleness/improve ductility ✓ induced during the hardening process. ✓ (2)
- 3.2 **Annealing:**
- To relieve internal stresses ✓ that may have been set up during working of metal.
 - To soften steel ✓ in order to facilitate the machining process.
 - To refine their grain structure. ✓
 - Reduce brittleness. ✓
 - Make the steel ductile. ✓ (Any 3 x 1) (3)
- 3.3 **Normalising temperature:**
- Above ✓ higher/upper critical temperature ✓
 - Above ✓ AC₃ line. ✓ (Any 1 x 2) (2)
- 3.4 **Spark pattern for carbon steels:**
- 3.4.1 High-carbon steel ✓ (1)
- 3.4.2 Low-carbon steel / Mild steel ✓ (1)
- 3.4.3 Cast-iron ✓ (1)
- 3.5 **Carbon diagram:**
- A. Temperature range / °C ✓
 - B. AC₃ line / Higher/upper critical temperature line ✓
 - C. AC₁ line / Lower critical temperature line ✓
 - D. Carbon content / % carbon ✓ (4)
- [14]

QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)

4.1	A ✓	(1)
4.2	C ✓	(1)
4.3	A ✓	(1)
4.4	A ✓	(1)
4.5	A ✓	(1)
4.6	C ✓	(1)
4.7	D ✓	(1)
4.8	D ✓	(1)
4.9	D ✓	(1)
4.10	C ✓	(1)
4.11	C ✓	(1)
4.12	B ✓	(1)
4.13	A ✓	(1)
4.14	D ✓	(1)
		[14]

QUESTION 5: TERMINOLOGY (TEMPLATES) (SPECIFIC)

5.1 Template machine tools:

- Planer ✓
- Circular saw ✓
- Drilling machine ✓
- Jig saw ✓
- Sanding machine ✓
- Shears for cutting cardboard ✓
- Any other appropriate machine tools. ✓


(Any 4 x 1) (4)

5.2 Roof truss:

- A. Purlin ✓
- B. Rafter ✓
- C. Bracing member ✓
- D. Main tie / Tie beam ✓
- E. Gusset plate ✓


(5)

5.3 Welding Symbol:




5.4 Supplementary symbols:

5.4.1



5.4.2



5.4.3



5.5 **Steel ring material:**

$$\text{Mean } \varnothing = \text{Outside Diameter} - \text{plate thickness}$$

$$\begin{aligned} & \checkmark \quad \checkmark \\ & = 600 - 30 \\ & = 570 \text{ mm } \checkmark \end{aligned}$$

$$\text{Mean circumference} = \pi \times \text{mean } \varnothing$$

$$\begin{aligned} & = \pi \times 570 \quad \checkmark \\ & = 1790,71 \text{ mm} \end{aligned}$$

$$\begin{aligned} & \text{OR} \quad \checkmark \\ & = 1791 \text{ mm} \end{aligned}$$

(5)
[23]

QUESTION 6: TOOLS AND EQUIPMENT (SPECIFIC)


- 6.1 **Manual guillotine:**
A – Spring loaded down pedal/Foot pedal ✓
B – Cutting table ✓
C – Pressure plate/Blade guard ✓ (3)
- 6.2 **Tap wrenches:**
• T- handle / Double handle tap wrench. ✓
• Single handle tap wrench/Ratchet tap wrench. ✓ (2)
- 6.3 **Angle grinders:**
• Cutting ✓
• Grinding ✓
• Polishing ✓
• Sanding ✓ (Any 3 x 1) (3)
- 6.4 **Advantages of Inverter:**
Inverters are able to weld a wider variety ✓ of materials ✓ than conventional AC welding machines. (2)
- 6.5 **Spot welding:**
• Does not use consumable electrodes ✓
• Efficient ✓
• Quick welding process ✓
• Ideal for mass production ✓
• Cost effective ✓
• Ideal for lightweight/thinner material ✓
• It can be used on a variety of metals ✓
• Ensure uniform joints ✓ (Any 2 x 1) (2)
- 6.6 **MIG welding procedures:**
• Forehand ✓
• Perpendicular ✓
• Backhand ✓ (3)
- 6.7 **Plasma cutting:**
Plasma cutting is a process that cuts through electrically conductive ✓ material by means of an accelerated jet ✓ of hot plasma. ✓ (3)

[18]

QUESTION 7: FORCES (SPECIFIC)

7.1 Steel framework:

**7.1.1 Space diagram:
 SCALE: 10 mm = 1 m**




NOTE: The sequence of Bow's notation can start in any position, but must maintain clockwise rotation.

(7)

7.1.2

**Vector diagram:
 SCALE: 1 mm = 10 N**



MEMBER	MAGNITUDE
BD	510 N ✓
CD	590 N ✓
AD	590 N ✓

NB: Marker must redraw the diagrams according to the given scale.
 When marking, use a tolerance of ± 2 mm.

(8)

7.2 Stress and Strain:

7.2.1 Cross sectional area:

$$\begin{aligned} \text{Area} &= \frac{\pi(D^2 - d^2)}{4} \\ &= \frac{\pi(0,06^2 - 0,05^2)}{4} \\ &= 8,64 \times 10^{-4} \text{m}^2 \quad \checkmark \end{aligned} \quad (3)$$

7.2.2 Stress:

$$\begin{aligned} \text{Stress} &= \frac{\text{Force/Load}}{\text{Area}} \\ &= \frac{500 \quad \checkmark}{8,639 \times 10^{-4} \quad \checkmark} \\ &= 578770,6911 \text{Pa} \\ &= 0,58 \text{MPa} \quad \checkmark \end{aligned} \quad (3)$$

7.2.3 Strain:

$$\begin{aligned} E &= \frac{\text{Stress}}{\text{Strain}} \\ \text{Strain} &= \frac{\text{Stress}}{E} \quad \checkmark \\ &= \frac{578770,6911 \quad \checkmark}{90 \times 10^9 \quad \checkmark} \\ &= 6,43 \times 10^{-6} \quad \checkmark \end{aligned} \quad (4)$$

7.3 Moments:




FIGURE 7.3

- 7.3.1 Reactions at LR and RR:
 Calculate LR
 Take moments about RR

$$\Sigma RHM = \Sigma LHM$$

$$\begin{aligned} LR \times 13 &= (250 \times 10,5) + (40 \times 8) + (60 \times 3) \\ &= 2625 + 320 + 180 \\ &= \frac{3125}{13} \\ LR &= 240,38 \text{ N } \checkmark \end{aligned}$$

- Calculate RR
 Take moments about LR

$$\Sigma LHM = \Sigma RHM$$

$$\begin{aligned} RR \times 13 &= (60 \times 10) + (40 \times 5) + (250 \times 2,5) \\ &= 600 + 200 + 625 \\ &= \frac{1425}{13} \\ RR &= 109,62 \text{ N } \checkmark \end{aligned}$$

(8)

7.3.2 **BENDING MOMENTS:**

$$BM_A = (240,38 \times 2,5) \checkmark$$

$$= 600,95 \text{ Nm } \checkmark$$

$$BM_B = (240,38 \times 5) - (250 \times 2,5) \checkmark$$

$$= 1201,90 - 625$$

$$= 576,90 \text{ Nm } \checkmark$$


$$BM_C = (240,38 \times 10) - (250 \times 7,5) - (40 \times 5) \checkmark$$

$$= 2403,8 - 1875 - 200$$

$$= 328,80 \text{ Nm } \checkmark$$

(6)

7.3.3 **BM diagram:**
SCALE: 1 mm = 10 Nm



NB: Marker must redraw the diagrams according to the given scale.

(6)
 [45]

QUESTION 8: JOINING METHODS (INSPECTION OF WELDS) (SPECIFIC)

8.1 Weld gauge:

To check:

- angle of preparation. ✓
- weld alignment. ✓
- fillet weld leg length/dimensions. ✓
- excess weld metal. ✓
- fillet weld throat. ✓
- undercut. ✓
- for porosity. ✓

(Any 4 x 1) (4)

8.2 Causes of welding defects:

8.2.1 Incomplete penetration:

- Too low welding current/amperage ✓
- Too slow travel speed ✓
- Incorrect torch angle ✓
- Insufficient root gap ✓
- Poor edge/joint preparation ✓
- Excessive root gap ✓
- Too fast travel speed ✓
- Too large electrode diameter ✓
- Arc length too long ✓
- Wet/contaminated electrodes ✓

(Any 2 x 1) (2)

8.2.2 Welding spatter:

- Disturbance in the molten weld pool ✓
- Too low welding current/amperage ✓
- Too high welding current/amperage ✓
- Arc length too long ✓
- Wet/contaminated electrode ✓
- Wrong polarity ✓
- Arc length too short ✓
- Incorrect type of electrode used ✓
- Incorrect included angle ✓
- Too fast travel speed ✓
- Surface contamination ✓
- Erratic wire feeding ✓

(Any 2 x 1) (2)

8.3 Prevention of welding defects:

8.3.1 Porosity:

- Cleaning the welding surface ✓
 - Ensuring that arc welding electrodes are dry ✓
 - Do not welding in a windy condition ✓
 - Insufficient root gap ✓
 - Ensure that the shielding gas supply is not interrupted ✓
 - Use correct type of electrode ✓
 - Reduce arc distance/length ✓
 - Reduce arc travel speed ✓
- (Any 2 x 1) (2)**

8.3.2 Undercutting:

- Maintain correct arc travel speed. ✓
 - By raising arc voltage. ✓
 - Using a leading electrode/torch angle. ✓
 - Reduce arc length ✓
- (Any 2 x 1) (2)**

8.4 Types of flames:

8.4.1 Neutral flame ✓ (1)

8.4.2 Carburising flame ✓ (1)

8.4.3 Oxidising flame ✓ (1)

8.5 Weld craters:

- Formed at the end of a weld run ✓ when the electrode ✓ is removed too soon. ✓
 - Not allowing ✓ enough filler ✓ material to fill the crater. ✓
 - Having ✓ a too big/erratic ✓ weaving action. ✓
- (Any 1 x 3) (3)**

8.6 Nick-break test:

- Make a hacksaw cut at both edges, through the center of the weld. ✓
 - Place specimen on two supports/bench vice. ✓
 - Use a sledgehammer to break the specimen in the area of the cuts. ✓
 - Inspect the exposed weld metal in the break ✓ for incomplete fusion, slag inclusion (or other welding defects). ✓
- (5)
[23]**

QUESTION 9: JOINING METHODS (STRESSES AND DISTORTION) (SPECIFIC)

- 9.1 **Elastic deformation:**
It is the ability of a joint/material to return to its original position/dimensions ✓
after the stresses have been relieved. ✓ (2)
- 9.2 **Shrinkage on steel:**
It is a form of plastic deformation where the metal has deformed ✓ as a result
of contraction on cooling. ✓ (2)
- 9.3 **Distortion:**
- 9.3.1 Transverse shrinkage ✓ (1)
- 9.3.2 Longitudinal shrinkage ✓ (1)
- 9.4 **Effects of shrinkage:**
- 9.4.1 **Electrode size:**
- Larger electrode size ✓ requires higher current and causes higher welding temperature ✓ that causes more deformation / shrinkage.
 - Smaller electrode size ✓ requires lower current and causes lower welding temperature ✓ that causes less deformation / shrinkage. (Any 1 x 2) (2)
- 9.4.2 **Welding speed:**
- Decreased ✓ welding speed tends to increase localised heat that increases distortion. ✓
 - Increased ✓ welding speed tends to decrease localised heat that decreases distortion. ✓ (Any 1 x 2) (2)
- 9.5 **Disadvantages of using jigs:**
It increases ✓ internal stresses ✓ in the welded joint because the metal's movement is restricted. ✓ (3)
- 9.6 **Carbon composition of steels:**
- 9.6.1 **Tool steel:**
- 0,71 – 1,5% ✓ (1)
- 9.6.2 **Spring steel:**
- 0,31 – 0,70% ✓ (1)
- 9.6.3 **Mild steel:**
- 0,07 – 0,30% ✓ (1)

9.7 **Quenching mediums:**

- Water ✓
- Oil ✓
- Brine (salt and water) ✓
- Molten metal salts ✓
- Sand ✓
- Air ✓
- Ash ✓
- Lime ✓
- Molten lead ✓
- Infused nitrogen air ✓

(Any 2 x 1)

**(2)
[18]**

QUESTION 10: MAINTENANCE (SPECIFIC)

10.1 **Insufficient lubrication:**

Pedestal drill:

- Rusting of components will occur ✓
- Movement between parts will be affected ✓
- Excessive wear and seizure of moving parts ✓
- Excessive heat generation ✓

(Any 3 x 1) (3)

10.2 **Overloading on a bench grinding machine:**

- Resulting in malfunction of the machine ✓
- Excessive wear and reduction of machine lifespan ✓
- Damage to grinding wheel ✓
- Damage to bearing on shaft ✓
- Damage to workpiece ✓

(Any 3 x 1) (3)

10.3 **General maintenance guidelines:**

- The machine should be tested for correct operation. ✓
- All guards must be in place and serviceable. ✓
- The machine must be securely fixed to the floor. ✓
- All bolts, nuts and grub screws must be in place and tight. ✓
- The machine must be in a clean condition. ✓
- Lubrication points should be serviced. ✓
- All moving parts should move freely. ✓


(Any 2 x 1) (2)
[8]

QUESTION 11: TERMINOLOGY (DEVELOPMENTS) (SPECIFIC)

11.1 Transformers:

Transformers are used to connect ✓ ducting sections ✓ of dissimilar shapes ✓ to each other. (3)

11.2 Hopper:



11.2.1 Square to rectangular ✓ hopper off ✓ centre (2)

11.2.2 True length A-2:

$$\begin{aligned}
 A-2 &= \sqrt{500^2 + 400^2 + 500^2} \\
 &= \sqrt{250000 + 160000 + 250000} \quad \checkmark \\
 &= 812,4 \text{ mm} \quad \checkmark
 \end{aligned}$$

(5)

11.2.3 True length B-2:

$$\begin{aligned}
 B-2 &= \sqrt{500^2 + 300^2 + 500^2} \\
 &= \sqrt{250000 + 90000 + 250000} \quad \checkmark \\
 &= 768,11 \text{ mm} \quad \checkmark
 \end{aligned}$$

(5)

11.3 **Truncated cone:**

11.3.1 **True length: A- B:**

$$\begin{aligned}A-B &= \frac{\pi \times D}{12} \checkmark \\ &= \frac{\pi \times 920}{12} \checkmark \\ &= 240,85 \text{ mm} \\ &= 241 \text{ mm} \checkmark\end{aligned}$$

(3)

11.3.2 **True length: 0-1:**

$$\begin{aligned}0-1 &= \frac{\pi \times D}{12} \checkmark \\ &= \frac{\pi \times 860}{12} \checkmark \\ &= 225,15 \text{ mm} \\ &= 225 \text{ mm} \checkmark\end{aligned}$$

(3)

[21]

TOTAL: 200