



basic education

Department:
Basic Education
REPUBLIC OF SOUTH AFRICA

**NATIONAL
SENIOR CERTIFICATE**

GRADE 12

MECHANICAL TECHNOLOGY

FEBRUARY/MARCH 2018

MARKING GUIDELINES

MARKS: 200

These marking guidelines consist of 21 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS

- 1.1 C ✓ (1)
- 1.2 C ✓ (1)
- 1.3 B ✓ (1)
- 1.4 D ✓ (1)
- 1.5 C ✓ (1)
- 1.6 D ✓ (1)
- 1.7 A ✓ (1)
- 1.8 A ✓ (1)
- 1.9 A ✓ (1)
- 1.10 B ✓ (1)
- 1.11 A ✓ (1)
- 1.12 C ✓ (1)
- 1.13 B ✓ (1)
- 1.14 A ✓ (1)
- 1.15 D ✓ (1)
- 1.16 A ✓ (1)
- 1.17 C ✓ (1)
- 1.18 A ✓ (1)
- 1.19 B ✓ (1)
- 1.20 A ✓ (1)
- [20]**

QUESTION 2: SAFETY

- 2.1 **Spring tester**
- Use correct attachments of the valve spring tester to compress the spring. ✓
 - Do not exceed the prescribed pressure. ✓
 - Ensure that the spring does not slip out. ✓
- (ANY 2 x 1) (2)**
- 2.2 **Welding helmet**
- To protect your eyes against the dangerous ultra-violet rays. ✓
 - To protect your skin against the dangerous ultra-violet rays. ✓
 - To protect your eyes against the sparks. ✓
 - To protect your skin against the sparks. ✓
- (ANY 1 x 1) (1)**
- 2.3 **Spot welding**
- To prevent the electrodes from overheating. ✓
- (1)**
- 2.4 **Testers**
- 2.4.1 **Brinell tester**
- The tester must be mounted on the rigid spot on a workbench ✓
 - The force must be applied at an angle of 90° to the test piece ✓
 - Do not exceed the prescribed load ✓
 - Make sure the test piece is placed securely into position ✓
- (ANY 1 x 1) (1)**
- 2.4.2 **Tensile tester**
- Make sure all safety guards are in place ✓
 - Do not exceed the prescribed load ✓
 - See that the test piece is securely placed in position ✓
 - Make sure the dial indicator is mounted properly ✓
- (ANY 1 x 1) (1)**
- 2.4.3 **Torsion tester**
- Fasten the tester to the workbench ✓
 - When you add pieces of different mass, you should attach them very gently otherwise you could get a skew reading of the torsion on the rod ✓
 - Get specification (torsion) of the different materials and of the size rods you would like test ✓
- (ANY 1 x 1) (1)**
- 2.5 **Bearing puller**
- Perpendicular or 90° to the bearing. ✓
- (1)**

2.6 Cylinder leakage tester

- 2.6.1
- To prevent damage to the seals and tester ✓
 - To ensure the correct reading ✓
- (ANY 1 x 1) (1)**
- 2.6.2
- To prevent damage to the tester and spark plug hole or injector hole ✓
 - To ensure the correct reading ✓
- (ANY 1 x 1) (1)**
[10]

QUESTION 3: TOOLS AND EQUIPMENT**3.1 Testers****3.1.1 Cylinder leakage tester**

- Is used to determine a leakage in the cylinder ✓.
- Determine the volume of leakage ✓ (2)

3.1.2 Fuel pressure tester

- Is used to test the fuel operating pressure in the system ✓
- Is used to test the fuel pressure in the fuel line that runs to the direct injection. ✓ (2)

3.1.3 Torsion tester

- Is used to investigate the relationship between momentum or torque applied to material ✓
- Is used to investigate influence of material length on torsional deflection. ✓ (2)

3.2 Reasons for high CO₂ reading

- Lean fuel mixture setting ✓
- Low compression ✓
- Faulty high tension leads ✓

(ANY 2 x 1) (2)

3.3 MIGS/MAGS-welding**3.3.1 Reasons for using inert gas during MIGS/MAGS welding**

- Stabilises the arc on the parent metal ✓
- Shields the arc and weld pool from atmospheric gases like oxygen ✓ (2)

3.3.2 Advantages of MIGS/MAGS welding

- Can weld in any position ✓
- Less operator skill required ✓
- Continuous welding can be done ✓
- Causes less deformation ✓
- Faster than arc welding ✓
- Minimal post weld cleaning ✓
- No slag removal is required ✓

(ANY 2 x 1) (2)
[12]

QUESTION 4: MATERIALS**4.1 Characteristics of structures****4.1.1 Austenite**

- Soft ✓
- Coarse grain structure ✓
- Non-magnetic ✓

(ANY 2 x 1) (2)**4.1.2 Ferrite**

- Soft ✓
- Ductile ✓
- Magnetic ✓

(ANY 2 x 1) (2)**4.2 Iron-carbon equilibrium diagram****4.2.1 Lower critical point (AC_1) of steel**

- The structure starts to change ✓✓

(2)**4.2.2 Higher critical point (AC_3) of steel**

- The structure turns into complete Austenite ✓✓
- The steel completely loses its magnetic properties ✓✓
- The structure turns into its finest grain size ✓✓

(ANY 1 x 2) (2)**4.3 Reasons to enhance properties of a crankshaft**

- To produce a hard face with a tough core. ✓
- To induce toughness ✓

(2)**4.4 Reasons for the tempering of a camshaft**

- To increase the lifespan of the camshaft ✓
- To eliminate brittleness caused by hardening. ✓

(ANY 2 x 1) (2)**4.5 Heat treatment process on piston rings**

- Hardening ✓

(1)**[13]**

QUESTION 5: TERMONOLOGY**5.1 Key dimensions****5.1.1 The width of the key**

$$\text{Width} = \frac{D}{4}$$

$$= \frac{120}{4}$$

$$= 30 \text{ mm}$$

✓

✓

(2)

5.1.2 The thickness of the key

$$\text{Thickness} = \frac{D}{6}$$

$$= \frac{120}{6}$$

$$= 20 \text{ mm}$$

✓

✓

(2)

5.1.3 The length of the key

$$\text{Length} = D \times 1.5$$

$$= 120 \times 1.5$$

$$= 180 \text{ mm}$$

✓

✓

(2)

5.2 Indexing

$$\text{Indexing} = \frac{40}{n}$$

$$= \frac{40}{124} \div \frac{2}{2}$$

$$= \frac{20}{62}$$

✓

✓

No full turns and 20 holes in a 62 hole circle

✓

(3)

5.3 Height of screw the screw thread

$$H = 0.866P$$

$$= 0.866 \times 3$$

$$= 2.6 \text{ mm}$$

✓

✓

(2)

5.4 **Gear terminology**

$$5.4.1 \quad \text{Addendum} = m = 3 \text{ mm} \quad \checkmark \quad (1)$$

$$5.4.2 \quad \text{Dedendum} = 1,157 m \quad \text{or} \quad = 1,25 m \\ = 1,157 \times 3 \quad \checkmark \quad = 1,25 \times 3 \quad \checkmark \\ = 3,47 \text{ mm} \quad \checkmark \quad = 3,75 \text{ mm} \quad \checkmark \quad (2)$$

$$5.4.3 \quad \text{Clearance} = 0,157 m \quad \text{or} \quad = 0,25 m \\ = 0,157 \times 3 \quad \checkmark \quad = 0,25 \times 3 \quad \checkmark \\ = 0,47 \text{ mm} \quad \checkmark \quad = 0,75 \text{ mm} \quad \checkmark \quad (2)$$

$$5.4.4 \quad \text{Module} = \frac{PCD}{T} \\ PCD = m \times T \quad \checkmark \\ = 3 \times 48 \quad \checkmark \\ = 144 \text{ mm} \quad \checkmark \quad (2)$$

$$5.4.5 \quad OD = PCD + 2m \quad \checkmark \\ = 144 + 2(3) \\ = 144 + 6 \\ = 150 \text{ mm} \quad \checkmark \quad (2)$$

$$5.4.6 \quad \text{Cutting depth} = 2,157 m \quad \checkmark \quad \text{or} \quad = 2,25 m \quad \checkmark \\ = 2,157 \times 3 \quad \checkmark \quad = 2,25 \times 3 \\ = 6,47 \text{ mm} \quad \checkmark \quad = 6,75 \text{ mm} \quad \checkmark \quad (2)$$

$$5.4.7 \quad \text{Circular pitch} = m \times \pi \quad \checkmark \\ = 3 \times \pi \\ = 9,42 \text{ mm} \quad \checkmark \quad (2)$$

5.5 **Setting of the lathe and cutting tool to cut a metric V-screw thread:**

- Set the lathe to the correct speed for screw cutting ✓
- Set the lead screw according to the required pitch ✓
- Set the dial gauge to position with the required worm gear ✓
- Set the compound slide to half the included angle of the thread (30°) ✓
- Set the cutting tool centre height and 90° to the work piece with the help of a centre gauge ✓
- Set cross slide and compound slide collars to zero with the tool touching the work piece ✓

(6)
[30]

QUESTION 6: JOINING METHODS**6.1 Welding defects****6.1.1 Slag inclusion**

- Welding speed too fast ✓
- Not removing the slag from the previous weld run before welding the next run ✓
- Current too low ✓

(ANY 2 x 1) (2)**6.1.2 Incomplete penetrations**

- Welding speed too fast ✓
- Faulty joint design ✓
- Electrode too large ✓
- Current too low ✓

(ANY 2 x 1) (2)**6.2 Atmospheric contamination during MIGS/MAGS welding**

- Inadequate shielding gas flow ✓
- Excessive shielding gas flow ✓
- Severely clogged nozzle ✓
- Damaged gas supply system ✓
- Excessive wind in the welding area ✓

(ANY 2 x 1) (2)**6.3 Nick break test**

- Make a hacksaw cut at both edges, through the centre of the weld ✓
- Place the saw-nicked specimen on two steel supports ✓
- Use a sledge hammer to break the specimen by striking it in the zone where you made the saw cuts ✓
- Defects like incomplete fusion, slag inclusion and brittleness will be exposed in the break ✓
- Any defects bring it to the attention to the welder to rectify it ✓

(5)**6.4 Reasons for destructive tests****6.4.1 Bend test**

To determine the ductility/elongation ✓✓ of the weld metal.

(2)**6.4.2 Machinability test**

To determine the welds hardness ✓ and its strength. ✓

(2)**6.5 X-ray test**

To detect internal defects in the weld metal ✓✓

(2)

6.6 Weld crater

Forms where welding is resumed at the bottom of the previous weld instead of on the top ✓✓ (2)

6.7 MIGS/MAGS welding

6.7.1 **Welding process**
MIGS/MAGS welding ✓ (1)


6.7.2 **Labelling**

- A. Parent metal ✓
- B. Arc ✓
- C. Electrode wire ✓
- D. Gas shroud ✓
- E. Shielding gas ✓

(5)
[25]

QUESTION 7: FORCES

7.1 Resultant



$$\begin{aligned} \Sigma HC &= 200 + 210 \cos 60^\circ - 190 \cos 40^\circ && \checkmark \checkmark \checkmark \\ &= 200 + 105 - 145,55 && \checkmark \\ &= 159,45 \text{ N} && (4) \end{aligned}$$

$$\begin{aligned} \Sigma VC &= 210 \sin 60^\circ + 190 \sin 40^\circ - 185 && \checkmark \checkmark \\ &= 181,87 + 122,13 - 185 && \checkmark \\ &= 119 \text{ N} && (3) \end{aligned}$$

OR

Horizontal components	Magnitudes	Vertical components	Magnitudes
200N	200 N ✓	210N Sin60°	181,87N ✓
210N	105 N ✓	190N Sin40°	122,13 N ✓
190N Cos40°	-145,45 N ✓	-185 N	-185 N
TOTAL	159,45 N ✓	TOTAL	119 N ✓

$$E^2 = HC^2 + VC^2$$

$$E = \sqrt{159,45^2 + 119^2}$$

$$E = 198,96 \text{ N}$$

$$\text{Tan } \theta = \frac{VC}{HC}$$

$$= \frac{119}{159,45}$$

$$= 36,73^\circ$$

$$E = 198,96 \text{ N } 36,73^\circ \text{ south of west}$$

OR

$$= 36^\circ 44' \text{ minutes south of west}$$


✓

✓

✓

✓

✓



(3)

(3)

7.2 Stress and Strain**7.2.1 Resistance area**

$$A = \frac{\pi(D^2 - d^2)}{4} \quad \checkmark$$

$$= \frac{\pi(0,056^2 - 0,038^2)}{4}$$

$$= 1,33 \times 10^{-3} m^2 \quad \checkmark \quad (2)$$

7.2.2 Stress

$$Stress = \frac{force}{area} \quad \checkmark$$

$$Stress = \frac{20 \times 10^3}{1,33 \times 10^{-3}} \quad \checkmark$$

$$= 15037593,98 Pa$$

$$Stress = 15,04 MPa \quad \checkmark \quad (3)$$

7.2.3 Strain

$$Strain = \frac{\Delta l}{OL} \quad \checkmark$$

$$Strain = \frac{50 - 49,975}{50} \quad \checkmark$$

$$Strain = \frac{0,025}{50}$$

$$= 0,5 \times 10^{-3} \quad \checkmark \quad (3)$$

7.2.4 Young's Modulus of Elasticity

$$Youngs Modulus of Elasticity = \frac{Stress}{Strain} \quad \checkmark$$


$$E = \frac{15,04 \times 10^6}{0,5 \times 10^{-3}} \quad \checkmark$$

$$= 30,08 \times 10^9 Pa$$

$$= 30,08 GPa \quad \checkmark \quad (3)$$

7.3 **Moments**

7.3

**Calculate B. Moments about A:**

$$\sum LHM = \sum RHM \quad \checkmark$$

$$(B \times 6) = (300 \times 1,5) + (850 \times 3) \quad \checkmark$$

$$\frac{6B}{6} = \frac{3000}{6}$$

$$B = 500 \text{ N} \quad \checkmark$$

Calculate A. Moments about B:

$$\sum RHM = \sum LHM \quad \checkmark$$

$$(A \times 6) = (850 \times 3) + (300 \times 4,5) + (600 \times 6) \quad \checkmark$$

$$6A = 2550 + 1350 + 3600$$

$$\frac{6A}{6} = \frac{7500}{6}$$

$$A = 1250 \text{ N} \quad \checkmark$$

(6)
[30]

QUESTION 8: MAINTENANCE**8.1 Reason using SAE 20W50**

This to ensure that the oil is able to satisfy the operational ✓ requirements over a range of temperature ✓ from start-up to running hot.

(2)

8.2 Maintain V-belt drive systems

- Check the contact surfaces of the pulley to prevent the belt from being damaged. ✓
- Check the belt condition and replace if it is worn. ✓
- Correct installation procedure must be followed. ✓
- Belt drives should be well guarded to prevent foreign objects to come into contact with the belts and pulleys. ✓
- Keep guard mesh free of papers, rags, etc. that can cause insufficient air flow. ✓
- Check that the belt deflection is according to specification. ✓
- Store replacement belts in a cool, well ventilated place. ✓
- Correct alignment of pulleys. ✓

(ANY 2 x 1)

(2)

8.3 Flash point

It is the lowest temperature ✓ at which the oil gives off vapours ✓ which can ignite. ✓

(3)

8.4 Maintaining cutting fluid

- Avoid contamination of the cutting fluid by draining and regularly replacing it. ✓
- Always clean the machine's splash tray of metal cutting after use. ✓
- Regularly wipe cutting fluid splashes of machine parts. ✓
- Ensure that the sump is topped up from time to time and check that there is sufficient flow of cutting fluid to the cutting tool. ✓

(ANY 2 x 1)

(2)

8.5 Functions of the clutch plate

- It provides friction between the flywheel and pressure plate. ✓
- It serves as a link between the clutch and the gearbox main shaft. ✓

(2)

8.6 Reasons for skimming the flywheel

- To remove the grooves caused by the clutch plate. ✓
- To ensure a full contact surface between the flywheel and the clutch plate. ✓
- To prolong the life of the clutch plate. ✓

(ANY 2 x 1)

(2)

8.7 **Properties of grease**

- It must be water resistant, it must not mix with water ✓
- Prevents rust/corrosion ✓
- Good for load pressures ✓
- High melting point ✓
- Low freezing point ✓
- Prevent gumming ✓
- Be able to lubricate ✓
- High viscosity ✓

(ANY 2 x 1)**(2)
[15]**

QUESTION 9: SYSTEMS AND CONTROL**9.1 Gear drives****9.1.1 Rotation frequency of input shaft**

$$\frac{N_A}{N_F} = \frac{T_B \times T_D \times T_F}{T_A \times T_C \times T_E}$$
$$N_A = \frac{T_B \times T_D \times T_F \times N_F}{T_A \times T_C \times T_E} \quad \checkmark$$
$$= \frac{36 \times 46 \times 80 \times 160}{20 \times 18 \times 42} \quad \checkmark$$
$$= 1401,90 \text{ r/min} \quad \checkmark \quad (3)$$

9.1.2 Velocity ratio

$$VR = \frac{N_A}{N_F} \quad \checkmark$$
$$VR = \frac{1401,90}{160} \quad \checkmark$$
$$= 8,76:1 \quad \checkmark \quad (2)$$

9.2 **Belt drives**9.2.1 **Rotation frequency of driver pulley**

$$N_{DR} \times D_{DR} = N_{DN} \times D_{DN}$$

$$N_{DR} = \frac{N_{DN} \times D_{DN}}{D_{DR}} \quad \checkmark$$

$$= \frac{733,33 \times 0,36}{0,24} \quad \checkmark$$

$$= 2000 \text{ r/min} \quad \checkmark$$

(3)

9.2.2 **Power transmitted**

$$P = \frac{(T_1 - T_2) \pi D n}{60}$$

$$P = \frac{(360 - 90) \pi \times 0,36 \times 733,33}{60} \quad \checkmark$$

$$= 3732,20 \text{ Watts}$$

$$= 3,73 \text{ kW} \quad \checkmark$$

(2)

9.2.3 **Belt speed**

$$\text{Belt speed} = \frac{\pi D N}{60}$$

$$= \frac{\pi \times 0,36 \times 733,33}{60} \quad \checkmark$$

$$= 13,83 \text{ m.s}^{-1} \quad \checkmark$$

(2)

9.3 **Hydraulics**9.3.1 **Fluid pressure**

$$A_B = \frac{\pi D^2}{4}$$

$$= \frac{\pi 0,04^2}{4} \quad \checkmark$$

$$= 1,26 \times 10^{-3} \text{ m}^2 \quad \checkmark$$

$$P_B = \frac{F}{A_B} \quad \checkmark$$

$$= \frac{275}{1,26 \times 10^{-3}} \quad \checkmark$$

$$= 218253,97 \text{ Pa}$$

or \checkmark

$$= 218,25 \text{ kPa} \quad (5)$$

9.3.2 **Diameter of piston B**

$$P_B = P_A$$

$$P_B = \frac{F_B}{A_B}$$

$$A_B = \frac{F_B}{P_B} \quad \checkmark$$

$$A_B = \frac{5,56 \times 10^3}{218,25 \times 10^3} \quad \checkmark$$

$$A_B = 25,48 \times 10^{-3} \text{ m}^2$$

$$A_B = \frac{\pi D^2}{4}$$

$$D_B = \sqrt{\frac{A_B \times 4}{\pi}} \quad \checkmark$$

$$= \sqrt{\frac{25,48 \times 10^{-3} \times 4}{\pi}} \quad \checkmark$$

$$= 0,18 \text{ m}$$

or \checkmark

$$= 180 \text{ mm} \quad (4)$$

- 9.4 **ABS**
ABS prevents wheels from skidding ✓ when breaking hard ✓ in difficult conditions. (2)
- 9.5 **ECU**
Electronic Control Unit ✓ (1)
- 9.6 **Traction Control**
- Prevent wheels from spinning. ✓
 - Improves road holding ✓
- (ANY 1 x 1) (1)**
[25]

QUESTION 10: TURBINES10.1 **Reaction turbines**

- Francis ✓
- Kaplan ✓
- Tyson ✓
- Gorlov ✓

(ANY 2 x 1) (2)10.2 **Supercharger boost**

Boost refers to the increase in intake manifold pressure ✓ that exceeds normal atmospheric pressure ✓

(2)

10.3 **Blowers**

- Roots ✓
- Centrifugal ✓
- Vane-type ✓
- Twin screw type ✓

(ANY 2 x 1) (2)10.4 **Gas turbine**

- A = Clean air inlet ✓
- B = Compression ✓
- C = Combustion ✓
- D = Exhaust ✓
- E = Turbine ✓
- F = Combustion chamber ✓

(6)

10.5 **Application of a gas turbine**

- Jet engines ✓
- Naval ships ✓
- Hi-performance vehicles and boats ✓
- Generating electricity ✓

(ANY 2 x 1) (2)10.6 **Advantages of a gas turbine**

- Less complex than internal combustion piston engines ✓
- Only one moving part (Common shaft for: compressor and turbine) ✓
- Operate at higher revolutions per minute ✓

(ANY 2 x 1) (2)10.7 **Waste gate**

A waste gate is a valve that diverts exhaust gases away from the turbine wheel ✓ to regulate the turbine/compressor speed and boost. ✓

(2)

10.8 **Oil cooler**

To cool the oil ✓ that lubricates the turbocharger bearings and shaft. ✓

(2)

[20]**TOTAL: 200**